MESH-VIEW SOFTWARE [MESH-VIEW]

Mesh-View is a tool that can be utilized for site surveys, simple data logging in CSV format, and as a verification tool for System Integrators. Compatible with all MESH-869 Series hardware.

Key features:

- *Supports MESH-869 Series Receivers & Sensors:*
  - *Industrial Pulse [MESH-EP-01]*
  - *Industrial Temperature [MESH-ET-01]*
  - *Industrial Contact Sensor [MESH-EC-01]*
  - *Room Temperature [MESH-IT-01]*
  - *Room Humidity/Temperature [MESH-IHT-01]*
- *Log to CSV*
- *Signal Strength Indication*



No.	Tx. Type	Tx. Add	Rcvd. Time	Value 1	Value 2	S_Level	Tx Ctr	Version	Status
1	PT1000 Temperature	125	13:21:38	23.00 degC	0.0	10	3	6	OK
2	Alarm	165	13:22:00	28		11	11	6	OK - CH1:OFF
3	PT1000 Temperature	120	13:21:45	23.00 degC	0.0	10	7	6	OK
4	Humidity / Temp	103A	13:22:05	-22.57 degC	64.00 %	9	10	6	OK
5	Humidity/Temp(Raw)	103B	13:22:05	-22.58 degC	56.76 %	9	10	6	OK
6	Alarm	161	13:21:26	12		9	15	6	OK - CH1:OFF
7	Alarm	168	13:21:55	750		11	11	6	OK - CH1:OFF
8	Humidity / Temp	104A	13:18:40	07.70 degC	33.00 %	9	9	6	OK
9	Humidity/Temp(Raw)	104B	13:18:40	07.70 degC	31.87 %	9	9	6	OK
10	Humidity / Temp	9A	13:18:44	22.69 degC	59.00 %	9	0	6	OK
11	Humidity/Temp(Raw)	9B	13:18:44	22.69 degC	50.75 %	9	0	6	OK
12	PT1000 Temperature	138	13:22:17	23.60 degC	0.0	11	14	6	OK
13	PT1000 Temperature	140	13:18:54	23.10 degC	0.0	11	11	6	OK
14	PT1000 Temperature	117	13:19:00	22.90 degC	0.0	10	5	6	OK
15	PT1000 Temperature	139	13:19:01	23.30 degC	0.0	10	12	6	OK
16	PT1000 Temperature	119	13:19:04	-26.70 degC	0.0	9	11	6	OK
17	PT1000 Temperature	146	13:19:06	23.10 degC	0.0	11	3	6	OK
18	PT1000 Temperature	114	13:19:09	06.70 degC	0.0	8	11	6	OK
19	Alarm	162	13:19:11	14		8	11	6	OK - CH1:OFF
20	PT1000 Temperature	141	13:19:20	23.30 degC	0.0	12	11	6	OK
21	PT1000 Temperature	135	13:19:26	23.50 degC	0.0	11	14	6	OK
22	Alarm	167	13:22:11	296		9	10	6	OK - CH1:OFF
23	Humidity / Temp	105A	13:19:31	22.95 degC	58.00 %	10	13	6	OK
24	Humidity/Temp(Raw)	105B	13:19:31	22.95 degC	58.36 %	10	13	6	OK
25	Humidity / Temp	101A	13:19:37	22.88 degC	57.00 %	10	6	6	OK
26	Humidity/Temp(Raw)	101B	13:19:37	22.88 degC	57.31 %	10	6	6	OK
27	PT1000 Temperature	111	13:19:43	23.00 degC	0.0	11	10	6	OK
28	PT1000 Temperature	110	13:19:43	23.30 degC	0.0	9	0	6	OK
29	PT1000 Temperature	112	13:19:44	22.70 degC	0.0	5	14	6	OK
30	Alarm	160	13:19:49	14		5	14	6	OK - CH1:OFF

PC Requirements	
Operating System	Windows XP, Vista, 7
CPU	Intel/AMD 1Ghz+
RAM	1GB
Free Hard Disk Space	10MB
Data Storage Type	CSV format
Connectivity	COM1 to COM8

*Specifications subject to change without notice.

For pricing, or any further, information please contact us.
Tel: +44 (0)845 9000 601 or visit our website.

omni INSTRUMENTS
www.omniinstruments.co.uk