TRX Load Cell Display





TEDS Enabled, 2 calibration ranges, works with all strain gauge transducers

• Lead Time: Ex-Stock

AT A GLANCE

- Engineering Unit Conversion
- TEDS Templates 33, 40, 41
- Sensitivities up to +/-480mV/V
- Environmental Protection: IP64
- PC-based Data Logging via Toolkit
- 2x AA Batteries or USB Powered
- Measurement rate up to 2,400 SPS

- Works with all Strain Gauge Bridge Transducers
- Two Calibration Channels
- TEDS Enabled
- Enhanced Calibration Options
- Works with 4-wire and 6-wire sensors
- 128 x 64 dot matrix display with backlight
- Configuration Toolkit Software (Windows only)

DESCRIPTION

The new **TEDS enabled** portable strain gauge sensor display TRX is a microprocessor-based portable display for all types of strain gauge bridge sensors with an output sensitivity from 0.5mV/V right up to 480mV/V. It is a direct replacement for the TR150 handheld display, with additional channels and features.

The display can be used as a handheld device (like the TR150) and also comes with optional mounting accessories for desks, walls and magnetic equipment.

The basic version offers 2 calibration channels/ranges, allowing optimised calibration of bi-directional transducers to give the best possible accuracy in tension and compression (or clockwise and counter-clockwise in the case of torque transducers. Each channel also offers enhanced calibration options in the form of either a linearised calibration or a polynomial calibration to give even greater accuracy from your strain gauge-based transducer. Plus, it supports TEDS templates 33 (bridge sensors template), 40 (multiple data pairs), and 41 (calibration curve polynomial).

Once calibrated in your preferred engineering units, you can switch freely between various other engineering units according to your sensor type at the press of a button; i.e bar to psi (pressure), kg to Newtons (force), Nm to lb-ft (torque), and so on.

Whilst every effort has been made to ensure the accuracy of this specification, we cannot accept responsibility for damage, injury, loss or expense from errors or omissions. In the interest of technical improvement, this specification may be altered without notice

For pricing or any further information, please contact Omni Instruments Ltd.



Contact Details:

Tel: +44 1382 443000 Email: info@omni.uk.com

Website: www.omniinstruments.co.uk

Mailing Address: Unit 1, 14 Nobel Road, Wester Gourdie Industrial Estate, Dundee, DD2 4UH.



TRX Load Cell Display

The free downloadable toolkit software enables advanced calibration and configuration options as well a data logging via the free Toolkit software, while simple configuration and 2-point calibration can be easily done/completed using the front panel buttons.

Functions on the TRX include:

- Switching Between Engineering Units
- Range Selection
- Display Hold/Freeze
- Gross/Net indication selection
- Peak Hold selection
- Trough Hold selection
- TEDS support

TEDS Functionality

TEDS delivers a simple 'plug and play' technology. You simply connect a TEDS integrated sensor into the TRX and the information stored on the integrated TEDS chip transfers the critical calibration information to and from the connected TEDS devices.


TEDS equipment is interchangeable without having to recalibrate the devices. The TRX strain gauge display will remember the last 20 TEDS devices that have been connected to it.

The TEDS information that can be read by the TRX consists of the TEDS bridge sensors transducer template 33 which includes the sensor manufacturer, model, and serial numbers, the calibration template table 40 (maximum calibration points of 10) and the calibration curve template 41 (up to a maximum number of segments of 1 and a maximum number of coefficients = 10).

The TRX strain gauge display also gives the user the option to ignore the TEDS data and use the TRX calibration ranges instead.

The Display

128 x 64 monochrome dot matrix display with backlight. The display will change depending on the mode and options you have enabled. Below are some examples of a 3 value display and a simple display.





For pricing or any further information, please contact Omni Instruments Ltd.



Contact Details:

Tel: +44 1382 443000 Email: info@omni.uk.com

Website: www.omniinstruments.co.uk

Mailing Address: Unit 1, 14 Nobel Road, Wester Gourdie Industrial Estate, Dundee, DD2 4UH.



TECHNICAL SPECIFICATIONS

CHARACTERISTICS	Min	Typical	Max	Units	
Strain Gauge Measurement	6-wire			Can also accept a 4-wire input.	
Display				128 x 64 dot matrix display with backlight	
Resolution at 1 SPS		1,100,000 (20)		Counts (bit)	
Resolution at 10 SPS		550,000 (19)		Counts (bit) Noise-free at ±7.5 mV/V range	
Resolution at 2,400 SPS		6,500 (14.3)		Counts (bit)	
Linearity		±2		ppm/FSR In high-quality operating mode (Linearity error can be further reduced by device linearization calibration)	
Excitation	3.2	3.3	3.4	Vdc	
Drive Capability	85	-	10,000	Ohm	
Sensitivity	±7.5	-	±480	mV/V (Effective sensitivity from ±0.5mV/V with reduced resolution)	
Offset Temperature Stability		12		nV/°C At 2.5 mV/V	
Gain Temperature Stability		1	2	ppm/°C	
Internal Resolution		24		bit	
Display Resolution		128 x 64		Pixels	
Buzzer Acoustic Output		45		dB	
Power Supply	2x	2x 1.5V AA (LR6) batteries or USB powered		Operation with batteries rated below 1.5V is not guaranteed to provide specified performance.	
Power Consumption		35		mA (in normal measurement mode)	
Standby Current		75		μΑ	
Battery Life Low Quality 1Hz		220		Hrs	
Battery Life High Quality 1,200Hz		60		Hrs	
Operating Temperature Range	-10		+50	°C	
Storage Temperature Range	-20		+80	°C	
Operating Humidity Range	0		95	%RH	
Environmental Protection				IP64 (With connector mated or unmated)	
External Dimensions				L: 170 mm, W: 94 mm, H: 42 mm (excluding mated connector)	
Weight		365		g including batteries	

Whilst every effort has been made to ensure the accuracy of this specification, we cannot accept responsibility for damage, injury, loss or expense from errors or omissions. In the interest of technical improvement, this specification may be altered without notice

For pricing or any further information, please contact Omni Instruments Ltd.




Contact Details: Tel: +44 1382 443000 Email: info@omni.uk.com Mailing Address: Unit 1, 14 Nobel Road, Wester Gourdie Industrial Estate, Dundee, DD2 4UH.

Website: www.omniinstruments.co.uk





Product Dimensions



ORDERING CODES & OPTIONS

Core Product	Details	Example Result
TRX Portable Strain Gauge Display	Standard Version with 2 Calibration Ranges	TRX-A

Whilst every effort has been made to ensure the accuracy of this specification, we cannot accept responsibility for damage, injury, loss or expense from errors or omissions. In the interest of technical improvement, this specification may be altered without notice.

For pricing or any further information, please contact Omni Instruments Ltd.



Contact Details: Tel: +44 1382 443000 Email: info@omni.uk.com Mailing Address: Unit 1, 14 Nobel Road, Wester Gourdie Industrial Estate, Dundee, DD2 4UH.

Website: www.omniinstruments.co.uk