


CDI-IPO

ISOLATED PULSE OUTPUT FOR CDI FLOWMETERS

- Provides electrical isolation between the flowmeter and a receiving device.
- Wire to a PLC or counter as you would a relay contact.
- Mounts inside flowmeter



The pulse output built into CDI flowmeters is an opencollector transistor output that functions as a switch to the meter's ground. It does not provide electrical isolation between the meter and the receiving device. The IPO provides this isolation.

DESCRIPTION

The CDI 5200 IPO interface provides an opticallyisolated output that simulates a relay contact. The output floats with respect to the meter's ground, and eliminates the need for any direct electrical connection between the meter and the receiving device.

SPECIFICATIONS

Input power: 2 mA at 18 to 24 Vdc

Max load current: 600 mA

Blocking voltage: 60 V

Output resistance: 0.8 Ohms
Isolation voltage: 1500 Volts

INSTALLATION AND WIRING

Unscrew the cover of the meter and lift out the display circuit board. The blue jumper wire may be removed from the terminal block, if it is present. Install the 5200-IPO with its two pins in the PULSE and DISP + terminals, and tighten the screws. Connect the wires from the receiving device to the two terminals of the terminal block.

The two terminals are interchangeable. Do not connect a ground wire from the receiving device to the meter unless the meter is being powered by the receiving device.

Do not wire the IPO into a circuit in which the current could exceed 600 mA or the voltage could exceed 60 Volts. Do not connect the IPO between a voltage source and a common or neutral terminal without a suitable current-limiting resistor.

Whilst every effort has been made to ensure the accuracy of this specification, we cannot accept responsibility for damage, injury, loss or expense from errors or omissions. In the interest of technical improvement, this specification may be altered without notice

For pricing or any further information, please contact Omni Instruments Ltd.



Contact Details:

Tel: +44 1382 443000 Fax: +44 1382 453197 Email: info@omni.uk.com **Mailing Address:** Unit 1, 14 Nobel Road, Wester Gourdie Industrial Estate, Dundee, DD2 4UH.

Website: www.omniinstruments.co.uk